




# Packing instruction for Mod.5030 blank feet w/o rust protection (500sets)

- ①~⑧ are necessary parts.
- Please prepare ⑥and ⑦ without rust protection
- Please deliver the packing boxes ⑧ in the folded state.
- Please make the packing for each parts ①~⑧ separately.
- We do not need the locking nut, threaded bolt, nut and wing nut.

素材 : ①~④プラスチック、⑤~⑦鉄、⑧段ボール



Please deliver ⑥⑦without the rust protection ( without coating )  
and pack them separately.



The contents of 1set Mod.5030

①③④⑤⑥⑦ 4pcs each

② 8pcs

⑧ 1pc

We don't need the threaded bolt,  
nut and wing nut.  
They are replaced with the same item  
in stainless steel in Japan.

(D)

**MONTAGEANLEITUNG FUSSGESTELL ALLROUND MOD. 5030/5032**

(GB)

**INSTALLATION INSTRUCTION ALLROUND BATH PEDESTAL MOD. 5030/5032**

(F)

**INSTRUCTIONS D'INSTALLATION DES PIEDS DE LA BAIGNOIRE MOD. 5030/5032**

(I)

**ISTRUZIONI PER IL MONTAGGIO DEI PIEDINI DI SUPPORTO ALLROUND MOD. 5030/5032**